



AUDI A3 SPORTBACK: 1KAT548

Vinnumber:	WAUZZZ8V7FA140029	Versionname:	1.6 TDI ULTRA ATTRACTION SPORTBACK
First Registrationdate:	20/03/2015	Fiscalpower:	
Expertise Mileage:	120712	Power Kw:	81
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3605
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Rear parking sensors
Windows electric F	Type of Tow bar
Windows electric R	No Tow bar
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/15/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	-----	------------	-----

Total cost ex VAT	1048,23
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	325,68



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	380,20
---	--------



Sill outer L, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	342,35
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Rear window, Not original part, Remove lettering	0,00
--	------

