



VOLVO V60: 1GQI741

Vinnumber:	VV1FW848BE1201905	Versionname:	D2 Kinetic Powersh.115PK Aut.
First Registrationdate:	1/04/2014	Fiscalpower:	
Expertise Mileage:	138585	Power Kw:	84
Bodytype:	Break	Body color:	Red
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2413
Maintenance:	OVER 3737 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1379,43
Bumper F, Scratch(es), LI - Repair and paint (complete)			211,80



Door panel R L, Tear, E - Replace 114,00



Grill frame, Broken, E - Replace 343,63



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Scratch(es), E - Replace 0,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Maintenance, Maintenance, P - Check 0,00

