



SKODA Superb: 1WDA466

Vinnumber:	TMBJJ73T4D9033598	Versionname:	SUPERB COMBI GreenLin.Ambition DPF 105PK
First Registrationdate:	1/01/2020	Fiscalpower:	
Expertise Mileage:	187274	Power Kw:	77
Bodytype:	Break	Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3621
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options

Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	
Type of headlighting	Headlighting Halogen		Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Uniroyal: 1 mm	Fr.R.	Uniroyal: 1 mm
	Re.L.	Uniroyal: 1 mm	Re.R.	Uniroyal: 1 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			3864,90
Interior, Dirty, Cleaning			0,00






Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 362,02



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Registration Document, Missing, E - Replace 150,00

No pictures to display

Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16




Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09



Wing F R, Scratch(es), LI - Repair and paint (complete)

264,21



Roof, Chemical polution, LI - Repair and paint (complete)

577,80



Wing R R, Scratch(es), LI - Repair and paint (complete)

369,84

