



OPEL MOKKA: 1KSA315

Vinnumber:	W0LJD7EC2F4107670	Versionname:	1.6 CDTI 100KW ECOFLEX S/S COSMO
First Registrationdate:	19/06/2015	Fiscalpower:	
Expertise Mileage:	136571	Power Kw:	100
Bodytype:		Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1205
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Front parking sensors	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/18/95 H LightMetal			
Winter tyres:	Fr.L.	Vredestein: 1 mm	Fr.R.	Vredestein: 1 mm
	Re.L.	Vredestein: 3 mm	Re.R.	Vredestein: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	445,28
-------------------	--------

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), Smart repair	110,64
-------------------------------------	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rearview mirror housing R, Scratch(es), E - Replace	74,00
---	-------



Door moulding Lower R R, Scratch(es), Smart repair	110,64
--	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display