


FORD Focus: 1HSK741

Vinnumber:	WF0KXXGCBKEB71171	Versionname:	FOCUS BER ECONetic Trend 88g 105PK
First Registrationdate:	22/09/2014	Fiscalpower:	
Expertise Mileage:	166460	Power Kw:	77
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2524
Maintenance	12/04/2020		
Maintenance	184000KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Luggage cover
GPS storage	SD	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H Steel			
Summer tyres:	Fr.L.	Firestone: 7 mm	Fr.R.	Firestone: 7 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			0,00
Door R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Seat cover F L, Worn, Acceptable			0,00

No pictures to display

Instrument panel complete, No damage, Acceptable	0,00
--	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

No pictures to display

Bumper trim R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display