



**BMW 3 TOURING: KD7362**

|                                    |                   |              |                          |
|------------------------------------|-------------------|--------------|--------------------------|
| Vinnumber:                         | WBA3K11030F838822 | Versionname: | 2.0 318D (105KW) TOURING |
| First Registrationdate:            | 24/03/2015        | Fiscalpower: |                          |
| Expertise Mileage:                 | 67646             | Power Kw:    | 105                      |
| Bodytype:                          | Break             | Body color:  | Grey                     |
| Gearbox:                           | Automatic         | Paint type:  | Metalic                  |
| Transmission:                      | Back              | Rims summer: | Aluminium                |
| Fueltype:                          | Diesel            | Oil level:   | OK                       |
| Battery functioning:               | Yes               | Parking lot: | 1413                     |
| Number of doors:                   | 5                 |              |                          |
| Number of seats:                   | 5                 |              |                          |
| Number head rests:                 | 5                 |              |                          |
| Rims summer:                       | Aluminium         |              |                          |
| Category:                          | Passenger Car     |              |                          |
| Oil level:                         | OK                |              |                          |
| Registration Certificate Car (BE): | Yes               |              |                          |

**Options**

|                                |                         |
|--------------------------------|-------------------------|
| Radio CD                       | Central consol F        |
| GPS storage                    | Luggage cover           |
| GPS storage                    | HD Rear parking sensors |
| Windows electric F             | Type of Tow bar         |
| Windows electric R             | No Tow bar              |
| Cruise Control                 |                         |
| Steering wheel multifunctional |                         |
| Radio multimedia               |                         |
| Type of headlighting           | Headlighting Halogen    |
| Type of GPS                    | GPS big screen color    |
| Type of Lining                 | Lining fabrics          |
| Type of climate control        | Autom climate control   |

**Limited Technical Inspection**

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Power steering      | Yes |
| Idle position       | OK | Sound engine        | OK  |
| Engine startingtime | OK | Clutch test         | OK  |
| Exhaust gass        | OK | Wiper fluid level   | OK  |
| Handbrake           | OK | Transmission        | OK  |
|                     |    | Lighting            | OK  |
|                     |    | Wiperblades         | OK  |

**Degree of wear**

|                           |       |                   |       |                   |
|---------------------------|-------|-------------------|-------|-------------------|
| 205/90/16/98 H LightMetal |       |                   |       |                   |
| Winter tyres:             | Fr.L. | Continental: 5 mm | Fr.R. | Continental: 5 mm |
|                           | Re.L. | Continental: 7 mm | Re.R. | Continental: 7 mm |

**Assistance equipment**

|                             |       |
|-----------------------------|-------|
| Total cost ex VAT           | 75,00 |
| Door F R, Bad repair, Paint | 0,00  |



|                                   |      |
|-----------------------------------|------|
| Bonnet, Stone chip(s), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                             |      |
|-----------------------------|------|
| Door R R, Bad repair, Paint | 0,00 |
|-----------------------------|------|



|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                           |       |
|---------------------------|-------|
| Interior, Stain, Cleaning | 75,00 |
|---------------------------|-------|

