


MERCEDES A: TE5708

Vinnumber:	WDD1760121J307062	Versionname:	A 180 CDI BE Edition 109PK
First Registrationdate:	14/08/2014	Fiscalpower:	
Expertise Mileage:	118779	Power Kw:	80
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3423
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2525,54
Windscreen, Stone chip(s), E - Replace			487,20



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover F L, Missing, E - Replace	30,00
---------------------------------------	-------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

No pictures to display

Sill outer R, Scratch(es), LI - Repair and paint (complete)	310,50
---	--------



Door R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Floor covering F L, Burned, Smart repair	64,32
--	-------



Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	--------



Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08
---	--------





Covering interior A pillar L, Burned, Smart repair

110,64



Bumper R, Dent(s) and scratch(es), Le - Replace and paint

651,00

