



VOLKSWAGEN Crafter 35 MWB hoog dak: 1FLC516

Vinnumber:	WV1ZZZ2EZD6024294	Versionname:	CRAFTER 35 B/F MWB HR 109PK
First Registrationdate:	2/08/2013	Fiscalpower:	
Expertise Mileage:	151729	Power Kw:	80
Bodytype:	Transporter	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	LCV19
Number of doors	5		
Number of seats	3		
Number head rests	3		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	Rear parking sensors
	Type of Tow bar
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/16/115 R Steel			
Summer tyres:	Fr.L.	Other: 6 mm	Fr.R.
	Re.L.	Continental: 4 mm	Re.R.

Assistance equipment

Spare wheel	Yes
Total cost ex VAT	561,41
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	238,76





Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearlight R , Broken, E - Replace	91,50
-----------------------------------	-------



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

No pictures to display

Trunk door R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15
---	--------

