


VOLKSWAGEN Golf: 1HLF901

Vinnumber:	WVWZZZAUZEW387864	Versionname:	GOLF BER Highline 105PK
First Registrationdate:	19/08/2014	Fiscalpower:	
Expertise Mileage:	141771	Power Kw:	77
Bodytype:		Body color	Blue
Gearbox:	MAN 5 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3506
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Central consol F
GPS storage	SD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	205/55/16/92 MS LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	481,50
Roof, Chemical polution, LI - Repair and paint (complete)	481,50



Windscreen, Scratch(es), E - Replace	0,00
--------------------------------------	------



Rear window, Scratch(es), E - Replace	0,00
---------------------------------------	------



Ignition key, Not functioning (well), Acceptable	0,00
--	------

No pictures to display