



VOLKSWAGEN GOLF VII: 1JUH193

Vinnumber:	WVWZZZAUZFW233581	Versionname:	1.6 TDI 66KW BMT TRENDLINE
First Registrationdate:	26/02/2015	Fiscalpower:	
Expertise Mileage:	52784	Power Kw:	66
Bodytype:	Hatchback	Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1322
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	SD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Winter tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 8 mm	Re.R.	Goodyear: 8 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			391,68
Wing F R, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Dent(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper F, Scratch(es), LI - Repair and paint (complete)			211,80



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Floor covering F L, Burned, Smart repair	64,32
--	-------



Tailgate, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	------

No pictures to display