


TOYOTA RAV4: 1GNU613

Vinnumber:	JTMZHV90D017378	Versionname:	RAV4 4x2 Active 124PK
First Registrationdate:	20/03/2014	Fiscalpower:	
Expertise Mileage:	125705	Power Kw:	91
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2823
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	225/65/17/102 T Steel			
	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	-----	------	-----

Total cost ex VAT	1029,55
Bonnet, Stone chip(s), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), E - Replace	415,20



Door R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Protection plate M, Tear, E - Replace	124,00



Door R R, Dent(s), LI - Repair and paint (complete)	366,35
---	--------



Engine protective plate, Hole, E - Replace	124,00
--	--------



Wing F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Repaired, Acceptable	0,00



Door panel R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	