


AUDI A3: 1HUE894

Vinnumber:	WAUZZZ8V4FA047260	Versionname:	A3 SB Ultra Attraction 110PK
First Registrationdate:	3/10/2014	Fiscalpower:	
Expertise Mileage:	178450	Power Kw:	81
Bodytype:	Hatchback	Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3121
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Rear parking sensors
Windows electric F	Type of Tow bar
Windows electric R	No Tow bar
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0	Jack	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1620,64
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Interior, Dirty, Cleaning

50,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Trunk lid covering R, Scratch(es), Smart repair

110,64



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80





Windscreen, Stone chip(s), E - Replace

0,00



Backrest cover F L, Scratch(es), Smart repair

64,32



Sill outer L, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

301,68



Wing F R, Dent(s), PDR - Paintless dent repair

63,00



Backrest cover F R, Scratch(es), Smart repair

64,32





Door F R, Dent(s), PDR - Paintless dent repair

63,00



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

