



PEUGEOT 2008: 1GBC919

Vinnumber:	VF3CU9HD8DY080472	Versionname:	2008 e-HDi Allure 115PK
First Registrationdate:	12/12/2013	Fiscalpower:	
Expertise Mileage:	86958	Power Kw:	84
Bodytype:	SUV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3223
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	195/60/16/89 V LightMetal			
	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			109,40
Door R L, Dent(s), Acceptable			0,00
No pictures to display			
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)			95,00



Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R polished, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R R polished, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Dent(s), Acceptable	0,00
No pictures to display	
Bonnet, Stone chip(s), Acceptable	0,00
No pictures to display	
Door F R, Dent(s), Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper moulding F M, Dent(s), E - Replace	14,40

