


SKODA OCTAVIA COMBI: 1KCB321

Vinnumber:	TMBJG9NE9F0176126	Versionname:	1.6 CRTDI 77KW GREENTEC ELEGANCE
First Registrationdate:	30/03/2015	Fiscalpower:	
Expertise Mileage:	147071	Power Kw:	77
Bodytype:		Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4230
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L
GPS storage		Sun Roof electric
GPS storage	HD	Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

Summer tyres:	225/45/17/91 V LightMetal			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	403,56
Wing R L, Scratch(es), Acceptable	0,00



Door R L, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F R, Scratch(es), I - Repair

100,00



Tyre F R, Tear, Acceptable

0,00



Alloy rim R L, Scratch(es), I - Repair

100,00



Wing R R, Dent(s) and scratch(es), Acceptable

0,00



Alloy rim F L, Scratch(es), Acceptable

0,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Boot carpet, Stain, Cleaning

25,00



Bumper R, Scratch(es), Acceptable

0,00

