


AUDI A6: 1GRS270

Vinnumber:	WAUZZZ4G1EN106117	Versionname:	A6 BER 136PK
First Registrationdate:	10/04/2014	Fiscalpower:	
Expertise Mileage:	125052	Power Kw:	100
Bodytype:	Berline	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1427
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Front parking sensors
GPS storage	SD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/60/16/98 W LightMetal			
	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Vredestein: 8 mm	Re.R.	Vredestein: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			851,36
Bumper F, Scratch(es), LI - Repair and paint (complete)			254,16



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Engine protective plate, Hole, E - Replace	129,60
--	--------



Sill outer L, Scratch(es), LI - Repair and paint (complete)	372,60
---	--------

