



RENAULT Clio GRAND TOUR: 1HKP070

Vinnumber:	VF17R040H51353027	Versionname:	CLIO IV BRE Expression 75PK
First Registrationdate:	12/08/2014	Fiscalpower:	
Expertise Mileage:	112164	Power Kw:	55
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	GEEN MELDING	Parking lot	2528
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/65/15/88 T Steel				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1183,20
Dashboard, Scratch(es), E - Replace	600,00



Bumper F, Scratch(es), LI - Repair and paint (complete)	169,44
---	--------



Door R R, Chemical polution, Acceptable	0,00
---	------

No pictures to display

Door R L, Chemical polution, Acceptable	0,00
---	------

No pictures to display

Tires, Out of tolerance, Acceptable	0,00
-------------------------------------	------

No pictures to display

Roof, Chemical polution, 67 - Polish	0,00
--------------------------------------	------



Wing R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Windscreen, Stone chip(s), E - Replace	413,76
--	--------



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Floor covering F L, Damaged, Acceptable	0,00
---	------

No pictures to display