



FORD Fiesta: HX9150

Vinnumber:	WF0JXXGAJJCY17166	Versionname:	FIESTA BER Trend EConetic 87g.95PK
First Registrationdate:	8/11/2012	Fiscalpower:	
Expertise Mileage:	144561	Power Kw:	70
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3813
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Luggage cover
Windows electric F	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	175/65/15/92 MS Steel			
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			2099,36
Wing R R, Dent(s), PDR - Paintless dent repair			82,80



Door F R, Scratch(es), Acceptable		0,00
-----------------------------------	--	------

No pictures to display

Interior: Dirty, Cleaning		0,00
---------------------------	--	------

Interior, Day, Cleaning		71,36
		
Internal Boot Lining R, Hole, E - Replace		71,36
		
Door R L, Scratch(es), LI - Repair and paint (complete)		254,68
		
Door R R, Scratch(es), Acceptable		0,00
No pictures to display		
Tailgate, Scratch(es), Acceptable		0,00
No pictures to display		
Bumper trim R, Missing, E - Replace		19,06
		
Door F L, Scratch(es), LI - Repair and paint (complete)		254,68
No pictures to display		
Bumper F, Scratch(es), LI - Repair and paint (complete)		169,44
		
Rearview mirror housing R, Scratch(es), Acceptable		0,00
No pictures to display		
Wing R L, Dent(s), Acceptable		0,00
		
Roof, Chemical polution, LI - Repair and paint (complete)		385,20
		
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)		217,44



Wing F L, Scratch(es), LI - Repair and paint (complete)

176,14



Windscreen, Crack, E - Replace

413,76



Parcel shelf covering, Missing, E - Replace

54,80

