


MERCEDES C: 1GQE914

Vinnumber:	WDD2042021G306883	Versionname:	C BRE 220CDI BE Edition Avantgarde 163PK
First Registrationdate:	1/04/2014	Fiscalpower:	
Expertise Mileage:	115989	Power Kw:	120
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	A 195JOURS	Parking lot	2325
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	No GPS	Type of Tow bar	No Tow bar
Type of Lining	Lining semi-artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Vredestein: 8 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Vredestein: 8 mm	Re.R.	Vredestein: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1186,76
Rearview mirror housing R, Scratch(es), Acceptable			0,00



Wing R R, Dent(s), Acceptable

0,00



Wing R L, Scratch(es), Acceptable

0,00



Backrest cover F L, Worn, Acceptable

0,00



Sill outer L, Scratch(es), It - Spot repair

115,56



Windscreen, Stone chip(s), Windscreen repair

58,80



Alloy rim F L, Scratch(es), E - Replace

235,20



Alloy rim F R, Scratch(es), E - Replace

235,20



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Steering wheel, Worn, Acceptable

0,00



Alloy rim R L, Scratch(es), E - Replace

235,20



Door F L, Scratch(es), Acceptable

0,00



Tailgate, Scratch(es), Acceptable

0,00

