


PEUGEOT 5008: 1LCX951

Vinnumber:	VF30EBHXMFS129612	Versionname:	1.6 BLUEHDI S&S 85KW ACTIVE
First Registrationdate:	24/08/2015	Fiscalpower:	
Expertise Mileage:	102001	Power Kw:	85
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4401
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Panoramic roof	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/55/16/93 H LightMetal			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Fulda: 5 mm	Re.R.	Fulda: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1036,12
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)	115,56
---	--------



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)	115,56
---	--------



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

