



|                                    |                          |              |                                   |
|------------------------------------|--------------------------|--------------|-----------------------------------|
| <b>BMW 5: 1GVG495</b>              |                          |              |                                   |
| Vinnumber:                         | <b>WBA5J31060D073379</b> | Versionname: | <b>5 TOURING 520dA 184PK Aut.</b> |
| First Registrationdate:            | <b>9/05/2014</b>         | Fiscalpower: |                                   |
| Expertise Mileage:                 | <b>68448</b>             | Power Kw:    | <b>135</b>                        |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Blue</b>                  |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                    |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                  |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                         |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4409</b>                       |
| Number of doors:                   | <b>5</b>                 |              |                                   |
| Number of seats:                   | <b>5</b>                 |              |                                   |
| Number head rests:                 | <b>5</b>                 |              |                                   |
| Rims summer:                       | <b>Aluminium</b>         |              |                                   |
| Category:                          | <b>Passenger Car</b>     |              |                                   |
| Oil level:                         | <b>OK</b>                |              |                                   |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                   |

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| <b>Options</b>                 |                              |                       |                   |
| Radio CD                       |                              | Seats electric F L    |                   |
| GPS storage                    |                              | Seats electric F R    |                   |
| GPS storage                    | <b>HD</b>                    | Sun Roof electric     |                   |
| Windows electric F             |                              | Panoramic roof        |                   |
| Windows electric R             |                              | Central consol F      |                   |
| Cruise Control                 |                              | Luggage cover         |                   |
| Steering wheel multifunctional |                              | Front parking sensors |                   |
| Seats F heated                 |                              | Rear parking sensors  |                   |
| Radio multimedia               |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Type of headlighting           | <b>Headlighting LED</b>      |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining leather</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |
| Head-up Display                |                              |                       |                   |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                |                           |                   |       |                   |
|----------------|---------------------------|-------------------|-------|-------------------|
| Degree of wear |                           |                   |       |                   |
| Summer tyres:  | 245/45/18/96 W LightMetal |                   |       |                   |
|                | Fr.L.                     | Continental: 5 mm | Fr.R. | Continental: 5 mm |
|                | Re.L.                     | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

|                                                                |          |  |                |
|----------------------------------------------------------------|----------|--|----------------|
| <b>Assistance equipment</b>                                    |          |  |                |
| Number of charging cables (normal)                             | <b>0</b> |  |                |
| Number of charging cables (rapid charge)                       | <b>0</b> |  |                |
| <b>Total cost ex VAT</b>                                       |          |  | <b>2132,20</b> |
| <b>Bumper R, Scratch(es), LI - Repair and paint (complete)</b> |          |  | <b>254,16</b>  |



Tyre F L, Tear, E - Replace

153,60



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)

264,21



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00





Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

264,21



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84

