


SKODA OCTAVIA COMBI: 1JUS356

Vinnumber:	TMBJF7NE8F0176092	Versionname:	1.6 CRTDI 66KW AMBITION
First Registrationdate:	2/03/2015	Fiscalpower:	
Expertise Mileage:	155340	Power Kw:	66
Bodytype:		Body color	Beige
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2823
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	Tow bar removable
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	925,89
Wheel cover F R, Scratch(es), E - Replace	30,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing R R, Scratch(es), It - Spot repair

115,56



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18




Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace

30,00



Bonnet, Dent(s), Acceptable

0,00

No pictures to display