



MERCEDES GLA: 1GWM620				
Vinnumber:	WDC1569081J017527	Versionname:	GLA 200 CDI 136PK	
First Registrationdate:	20/05/2014	Fiscalpower:		
Expertise Mileage:	106242	Power Kw:	100	
Bodytype:		Body color	Grey	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Back	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Maintenance	BINNEN 129 DAGEN	Parking lot	3223	
Maintenance	OK			
Battery functioning	Yes			
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Front parking sensors		
Steering wheel multifunctional		Rear parking sensors		
Radio multimedia		Type of Tow bar	No Tow bar	
Type of headlighting	Headlighting Xenon			
Type of GPS	GPS big screen color			
Type of Lining	Lining artificial leather			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	235/50/18/97 V LightMetal			
	Fr.L.	Yokohama: 6 mm	Fr.R.	Yokohama: 6 mm
	Re.L.	Yokohama: 5 mm	Re.R.	Yokohama: 5 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			591,76	
Door F L, Repaired, No repair			0,00	



Door R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Repaired, No repair	0,00



Door F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper corner R L, Scratch(es), It - Spot repair	115,56



Wing F L, Repaired, No repair	0,00
-------------------------------	------



Centre console, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), E - Replace	420,00



Wing R L, Repaired, No repair	0,00
-------------------------------	------



Door F L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Mirror side blinker R, Broken, E - Replace	31,20



Bumper corner R R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Ceiling, Stain, Cleaning	25,00





Seat cover F L, Worn, Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	