


**SKODA Superb: 1HJH609**

|                                    |                          |              |                                              |
|------------------------------------|--------------------------|--------------|----------------------------------------------|
| Vinnumber:                         | <b>TMBJJ93T2F9010934</b> | Versionname: | <b>SUPERB COMBI GreenLine Elegance 105PK</b> |
| First Registrationdate:            | <b>1/08/2014</b>         | Fiscalpower: |                                              |
| Expertise Mileage:                 | <b>183216</b>            | Power Kw:    | <b>77</b>                                    |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Grey</b>                                  |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                               |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                             |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                    |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4706</b>                                  |
| Number of doors:                   | <b>5</b>                 |              |                                              |
| Number of seats:                   | <b>5</b>                 |              |                                              |
| Number head rests:                 | <b>5</b>                 |              |                                              |
| Rims summer:                       | <b>Aluminium</b>         |              |                                              |
| Category:                          | <b>Passenger Car</b>     |              |                                              |
| Oil level:                         | <b>OK</b>                |              |                                              |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                              |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Seats R heated               |
| Windows electric F             | Seats electric F L           |
| Windows electric R             | Seats electric F R           |
| Cruise Control                 | Sun Roof electric            |
| Steering wheel multifunctional | Central consol F             |
| Seats F heated                 | Luggage cover                |
| Radio multimedia               | Front parking sensors        |
| Type of headlighting           | Rear parking sensors         |
| Type of GPS                    | Type of Tow bar              |
| Type of Lining                 | <b>No Tow bar</b>            |
| Type of climate control        | <b>Autom climate control</b> |
|                                | <b>Headlighting Xenon</b>    |
|                                | <b>GPS big screen color</b>  |
|                                | <b>Lining leather</b>        |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                |                |
|----------------------------------|-------|----------------|----------------|
| <b>205/55/16/91 V LightMetal</b> |       |                |                |
| Summer tyres:                    | Fr.L. | Michelin: 4 mm | Fr.R.          |
|                                  | Re.L. | Michelin: 4 mm | Re.R.          |
|                                  |       |                | Michelin: 4 mm |

**Assistance equipment**

|                                          |            |      |            |
|------------------------------------------|------------|------|------------|
| Spare wheel                              | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|                                                              |       |
|--------------------------------------------------------------|-------|
| Total cost ex VAT                                            | 95,00 |
| Bumper F, Scratch(es), Acceptable                            | 0,00  |
| <i>No pictures to display</i>                                |       |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |



|                                        |      |
|----------------------------------------|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
| No pictures to display                 |      |
| Wing F R, Scratch(es), Acceptable      | 0,00 |
| No pictures to display                 |      |
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
| No pictures to display                 |      |
| Wing R R, Scratch(es), Acceptable      | 0,00 |
| No pictures to display                 |      |