


**BMW 1: CH8753**

Vinnumber:	<b>WBA1C11050E885635</b>	Versionname:	<b>1 BER HATCH 118d 143PK</b>
First Registrationdate:	<b>29/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>154766</b>	Power Kw:	<b>105</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1129</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	<b>No Tow bar</b>
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>No GPS</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	746,32
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Repaired, Acceptable

0,00

*No pictures to display*

Headlight L, Scratch(es), Acceptable

0,00



Mirror side blinker L, Broken, E - Replace

30,00



Rearview mirror housing L, Scratch(es), Smart repair

110,64



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

301,68



Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Door panel R L, Tear, E - Replace

114,00



Seat cover F L, Stain, Acceptable

0,00



Wing R R, Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim F L, Scratch(es), Acceptable

0,00



Bonnet, Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*