



KIA SPORTAGE: 1NSF331

Vinnumber:	U5YPH815AGL048778	Versionname:	1.7 CRDI 2WD ISG ECODYNAMICS BUS. FUSION
First Registrationdate:	14/04/2016	Fiscalpower:	
Expertise Mileage:	155158	Power Kw:	85
Bodytype:	SUV	Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2531
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Seats R heated
Windows electric R	Seats electric F L
Cruise Control	Seats electric F R
Steering wheel multifunctional	Central consol F
Seats F heated	Luggage cover
Radio multimedia	Front parking sensors
Type of headlighting	Rear parking sensors
Type of GPS	Type of Tow bar
Type of Lining	Tow bar fixed
Type of climate control	
Headlighting Halogen	
GPS big screen color	
Lining leather	
Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/60/17/99 V LightMetal			
Summer tyres:	Fr.L.	Semperit: 3 mm	Fr.R.
	Re.L.	Semperit: 3 mm	Re.R.

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	433,91
-------------------	--------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bonnet, Dent(s), Acceptable	0,00
No pictures to display	
Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	
Door panel R L, Scratch(es), Acceptable	0,00
No pictures to display	
Trunk lid covering R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing F R, Rust, It - Spot repair	115,56

