


**OPEL Astra: 1CDU131**

|                                    |                          |              |                                         |
|------------------------------------|--------------------------|--------------|-----------------------------------------|
| Vinnumber:                         | <b>W0LPD8EA6C8014279</b> | Versionname: | <b>ASTRA BRE ecoFLEX Enjoy FAP 95PK</b> |
| First Registrationdate:            | <b>27/10/2011</b>        | Fiscalpower: |                                         |
| Expertise Mileage:                 | <b>175256</b>            | Power Kw:    | <b>70</b>                               |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Silver</b>                           |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metallic</b>                         |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>                            |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                               |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1222</b>                             |
| Number of doors:                   | <b>5</b>                 |              |                                         |
| Number of seats:                   | <b>5</b>                 |              |                                         |
| Number head rests:                 | <b>4</b>                 |              |                                         |
| Rims summer:                       | <b>Steel</b>             |              |                                         |
| Category:                          | <b>Passenger Car</b>     |              |                                         |
| Oil level:                         | <b>OK</b>                |              |                                         |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                         |

**Options**

|                                |                             |
|--------------------------------|-----------------------------|
| Radio CD                       | Central consol F            |
| Windows electric F             | Luggage cover               |
| Cruise Control                 | Rear parking sensors        |
| Steering wheel multifunctional | Type of Tow bar             |
| Radio multimedia               | <b>Tow bar fixed</b>        |
| Type of headlighting           | <b>Headlighting Halogen</b> |
| Type of GPS                    | <b>No GPS</b>               |
| Type of Lining                 | <b>Lining fabrics</b>       |
| Type of climate control        | <b>No climate control</b>   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Tires wear profile  | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Idle position       | <b>OK</b> | Power steering      | <b>Yes</b> |
| Engine startingtime | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
|                     |           | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                       |       |                       |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| Summer tyres: | <b>205/60/16/92 H Steel</b> |                       |       |                       |
|               | Fr.L.                       | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|               | Re.L.                       | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

**Assistance equipment**

|                                          |            |      |            |
|------------------------------------------|------------|------|------------|
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|                                                                   |         |
|-------------------------------------------------------------------|---------|
| Total cost ex VAT                                                 | 3150,46 |
| Rocker panel inner F L, Dent(s), LI - Repair and paint (complete) | 115,56  |



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Floor covering F L, Hole, Smart repair

64,32



Wheel cover F R, Deformed / Strained, E - Replace

30,00



Wheel cover R R, Broken, E - Replace

30,00



Ignition key, Broken, E - Replace

150,00



Seat cover F L, Stain, Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80





Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Quarter light F R, Broken, E - Replace 0,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bad repair, Acceptable 0,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Deformed / Strained, Le - Replace and paint 651,00



Door panel R L, Scratch(es), E - Replace 114,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display