


MERCEDES Sprinter 300: 1HHG866

Vinnumber:	WDB9066351S947193	Versionname:	SPRINTER 313 B/F LWB HR A3H2 129PK
First Registrationdate:	23/07/2014	Fiscalpower:	
Expertise Mileage:	170415	Power Kw:	95
Bodytype:	Transporter	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	LCV10
Number of doors	5		
Number of seats	3		
Number head rests	3		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Central consol F
Radio multimedia	Front parking sensors
Type of headlighting	Rear parking sensors
Type of GPS	Type of Tow bar
Type of Lining	No Tow bar
Type of climate control	
Headlighting Halogen	
No GPS	
Lining fabrics	
Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/16/115 S Steel			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare wheel	Yes
-------------	-----

Total cost ex VAT	1104,92
Trunk door R R, Dent(s) and scratch(es), It - Spot repair	115,56

No pictures to display

Bumper grille, Broken, E - Replace	30,30
------------------------------------	-------



Door moulding Lower R R, Scratch(es), E - Replace

91,50



Door R R, Dent(s), LI - Repair and paint (complete)

238,76



Sill outer R, Dent(s) and scratch(es), Le - Replace and paint

546,00



Door R L, Scratch(es), 67 - Polish

0,00



Trunk door R L, Dent(s), PDR - Paintless dent repair

82,80

