


**MERCEDES CLA SHOOTING BRAKE: 1LPA186**

|                                    |                          |              |                                             |
|------------------------------------|--------------------------|--------------|---------------------------------------------|
| Vinnumber:                         | <b>WDD1179081N308727</b> | Versionname: | <b>2.1 CLA 200 CDI URBAN SHOOTING BRAKE</b> |
| First Registrationdate:            | <b>3/11/2015</b>         | Fiscalpower: |                                             |
| Expertise Mileage:                 | <b>148356</b>            | Power Kw:    | <b>100</b>                                  |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Black</b>                                |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                              |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                            |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                   |
| Maintenance:                       | <b>OVER 2400 KM</b>      | Parking lot: | <b>3722</b>                                 |
| Maintenance:                       | <b>OK</b>                |              |                                             |
| Battery functioning:               | <b>Yes</b>               |              |                                             |
| Number of doors:                   | <b>5</b>                 |              |                                             |
| Number of seats:                   | <b>5</b>                 |              |                                             |
| Number head rests:                 | <b>1</b>                 |              |                                             |
| Rims summer:                       | <b>Aluminium</b>         |              |                                             |
| Category:                          | <b>Passenger Car</b>     |              |                                             |
| Oil level:                         | <b>OK</b>                |              |                                             |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                             |

**Options**

|                                |                                       |                       |                   |
|--------------------------------|---------------------------------------|-----------------------|-------------------|
| GPS storage                    |                                       | Central consol F      |                   |
| GPS storage                    | <b>SD</b>                             | Luggage cover         |                   |
| Windows electric F             |                                       | Front parking sensors |                   |
| Windows electric R             |                                       | Rear parking sensors  |                   |
| Cruise Control                 |                                       | Type of Tow bar       | <b>No Tow bar</b> |
| Steering wheel multifunctional |                                       |                       |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>             |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>           |                       |                   |
| Type of Lining                 | <b>Lining semi-artificial leather</b> |                       |                   |
| Type of climate control        | <b>Autom climate control</b>          |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                      |       |                      |
|---------------|----------------------------------|----------------------|-------|----------------------|
|               | <b>225/45/17/91 V LightMetal</b> |                      |       |                      |
| Summer tyres: | Fr.L.                            | <b>Pirelli: 3 mm</b> | Fr.R. | <b>Pirelli: 3 mm</b> |
|               | Re.L.                            | <b>Pirelli: 4 mm</b> | Re.R. | <b>Pirelli: 4 mm</b> |

**Assistance equipment**

|                                                                     |            |            |               |
|---------------------------------------------------------------------|------------|------------|---------------|
| Repair kit                                                          | <b>Yes</b> | Compressor | <b>Yes</b>    |
| Total cost ex VAT                                                   |            |            | <b>211,80</b> |
| Alloy rim R L polished, Scratch(es), Acceptable                     |            |            | <b>0,00</b>   |
| <i>No pictures to display</i>                                       |            |            |               |
| Rearview mirror housing L, Scratch(es), Acceptable                  |            |            | <b>0,00</b>   |
| <i>No pictures to display</i>                                       |            |            |               |
| Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) |            |            | <b>211,80</b> |



|                                                 |      |
|-------------------------------------------------|------|
| Alloy rim F R polished, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>                   |      |
| Door F L, Scratch(es), Acceptable               | 0,00 |
| <i>No pictures to display</i>                   |      |
| Trunk lid covering R, Scratch(es), Acceptable   | 0,00 |
| <i>No pictures to display</i>                   |      |
| Alloy rim R R polished, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>                   |      |
| Door R R, Bad repair, P - Check                 | 0,00 |
| <i>No pictures to display</i>                   |      |
| Rocker panel inner F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>                   |      |