



|                               |                   |              |                                        |
|-------------------------------|-------------------|--------------|----------------------------------------|
| RENAULT Grand Scenic: 1EZK059 |                   |              |                                        |
| Vinnumber:                    | VF1JZ14M648906961 | Versionname: | GR.SCENIC Energ.Business 5pl.FAP 110PK |
| First Registrationdate:       | 2/05/2013         | Fiscalpower: |                                        |
| Expertise Mileage:            | 78698             | Power Kwr:   | 81                                     |
| Bodytype:                     |                   | Body color   | Burgundy                               |
| Gearbox:                      | MAN 6 VIT         | Paint type   | Metalic                                |
| Transmission:                 | Front             | Rims summer  | Steel                                  |
| Fueltype:                     | Diesel            | Oil level    | OK                                     |
| Battery functioning           | Yes               | Parking lot  | 2113                                   |
| Number of doors               | 5                 |              |                                        |
| Number of seats               | 5                 |              |                                        |
| Number head rests             | 5                 |              |                                        |
| Rims summer                   | Steel             |              |                                        |
| Category                      | Passenger Car     |              |                                        |
| Oil level                     | OK                |              |                                        |

|                                |                      |                      |            |
|--------------------------------|----------------------|----------------------|------------|
| Options                        |                      |                      |            |
| Windows electric F             |                      | Central consol F     |            |
| Windows electric R             |                      | Luggage cover        |            |
| Cruise Control                 |                      | Rear parking sensors |            |
| Steering wheel multifunctional |                      | Type of Tow bar      | No Tow bar |
| Type of headlighting           | Headlighting Halogen |                      |            |
| Type of Lining                 | Lining fabrics       |                      |            |

|                              |    |                     |     |
|------------------------------|----|---------------------|-----|
| Limited Technical Inspection |    |                     |     |
| Airco functioning            | OK | Battery functioning | Yes |
| Tires wear profile           | OK | Power steering      | Yes |
| Idle position                | OK | Sound engine        | OK  |
| Engine startingtime          | OK | Clutch test         | OK  |
| Exhaust gass                 | OK | Wiper fluid level   | OK  |
| Handbrake                    | OK | Transmission        | OK  |
|                              |    | Lighting            | OK  |
|                              |    | Wiperblades         | OK  |

|                |                      |                |       |                |
|----------------|----------------------|----------------|-------|----------------|
| Degree of wear |                      |                |       |                |
| Summer tyres:  | 205/60/16/96 H Steel |                |       |                |
|                | Fr.L.                | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
|                | Re.L.                | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

|                                          |     |      |     |
|------------------------------------------|-----|------|-----|
| Assistance equipment                     |     |      |     |
| Emergency spare wheel                    | Yes | Jack | Yes |
| Number of charging cables (normal)       | 0   |      |     |
| Number of charging cables (rapid charge) | 0   |      |     |

|                                   |        |
|-----------------------------------|--------|
| Total cost ex VAT                 | 320,08 |
| Bumper R, Scratch(es), Acceptable | 0,00   |

|                                                       |        |
|-------------------------------------------------------|--------|
| No pictures to display                                |        |
| Bonnet, Scratch(es), LI - Repair and paint (complete) | 290,08 |



|                                           |       |
|-------------------------------------------|-------|
| Wheel cover F.R. Scratch(es), F - Replace | 30,00 |
|-------------------------------------------|-------|



Door F R, Dent(s), Acceptable

0,00

No pictures to display