


VOLKSWAGEN GOLF VARIANT: 1KRA300

Vinnumber:	WVWZZZAUZGP500395	Versionname:	1.6 TDI 66KW TRENDLINE
First Registrationdate:	12/06/2015	Fiscalpower:	
Expertise Mileage:	137918	Power Kw:	66
Bodytype:		Body color	Blue
Gearbox:	MAN 5 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4501
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2686,90
Wheel cover F R, Scratch(es), E - Replace	30,00



Bonnet, Hail damage, PDR - Hail

75,00



Tailgate, Hail damage, PDR - Hail

75,00



Door F L, Dent(s), LI - Repair and paint (complete)

366,35



Sill trim R R, Scratch(es), E - Replace

69,00



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

414,35





Windscreen, Scratch(es), E - Replace

487,20



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Roof pillar R, Hail damage, PDR - Hail

25,00



Roof, Hail damage, PDR - Hail

625,00



Seat cover F L, Dirty, Acceptable

0,00

No pictures to display