


BMW 3 TOURING: 1KPP834

Vinnumber:	WBA3L11000K177786	Versionname:	2.0 320D EFFICIENTDYN. (120KW) TOURING
First Registrationdate:	10/06/2015	Fiscalpower:	
Expertise Mileage:	200189	Power Kw:	120
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4220
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
GPS storage	Luggage cover	
GPS storage	HD	Rear parking sensors
Windows electric F	Type of Tow bar	No Tow bar
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/92 W LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1540,38
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Roof, Dent(s), Acceptable 0,00

No pictures to display

Door R L, Bad repair, Acceptable 0,00



Windscreen, Stone chip(s), Acceptable 0,00



Door F L, Bad repair, Acceptable 0,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bad repair, Acceptable 0,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

