



SKODA SUPERB COMBI: 1KTB002

Vinnumber:	TMBJJ73T3F9040741	Versionname:	1.6 CRTDI 77KW GREENLINE ELEGANCE
First Registrationdate:	26/06/2015	Fiscalpower:	
Expertise Mileage:	126971	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2412
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Seats R heated
Windows electric F	Seats electric F L
Windows electric R	Seats electric F R
Cruise Control	Sun Roof electric
Steering wheel multifunctional	Panoramic roof
Seats F heated	Central consol F
Type of headlighting	Luggage cover
Type of GPS	Front parking sensors
Type of Lining	Rear parking sensors
Type of climate control	Type of Tow bar
Headlighting Halogen	No Tow bar
GPS big screen color	
Lining leather	
Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 W LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Kleber: 8 mm	Re.R.	Kleber: 8 mm

Assistance equipment

Total cost ex VAT	2857,83
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16





Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

372,60



Rearlight R , Broken, E - Replace

132,00



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Door panel R L, Worn, E - Replace

44,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

362,02



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

264,21



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

369,84



Ignition key, Missing, E - Replace

150,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



No pictures to display