



AUDI A4 AVANT: 1NVS443

Vinnumber:	WAUZZZF46GA088453	Versionname:	2.0 TDI ULTRA 110KW S TRONIC
First Registrationdate:	9/05/2016	Fiscalpower:	
Expertise Mileage:	198637	Power Kw:	110
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4404
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.
	Re.L.	Dunlop: 4 mm	Re.R.

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	617,44
Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08



Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing F L, Scratch(es), It - Spot repair	115,56



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), Acceptable	0,00
No pictures to display	
Steering wheel, Worn, Acceptable	0,00
No pictures to display	
Rear window, Scratch(es), Acceptable	0,00
No pictures to display	