


BMW 4 GRAN COUP?: 1JXD327

Vinnumber:	WBA4D51010GT64207	Versionname:	2.0 418D (100KW) GRAN COUPE
First Registrationdate:	11/03/2015	Fiscalpower:	
Expertise Mileage:	139339	Power Kw:	100
Bodytype:	Coupé	Body color	Brown
Gearbox:	Automatic	Body color	BRUIN
Transmission:	Back	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	OK	Oil level	OK
Maintenance	21000 KM	Parking lot	3706
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
GPS storage	Front parking sensors	
GPS storage	Rear parking sensors	
Windows electric F	Type of Tow bar	No Tow bar
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 W LightMetal			
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT		211,80
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80

