


FORD Focus: 1GEZ756

Vinnumber:	WF0LXXGCBLEL52679	Versionname:	FOCUS CLIP. EConetic Titanium 88g 105PK
First Registrationdate:	21/01/2014	Fiscalpower:	
Expertise Mileage:	82330	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2621
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V Steel			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	661,86
-------------------	--------

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)	115,56
---	--------



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Rear window, Scratch(es), Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Chemical polution, 67 - Polish

0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace

30,00





Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Floor covering F L, Hole, Smart repair	64,32
--	-------



Sidewall panel RL, Missing, E - Replace	20,00
---	-------



Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display