



OPEL ASTRA: 1SEY681

Vinnumber:	W0LBD6EG9HG095889	Versionname:	1.6 CDTI 100KW EDITION AUTO
First Registrationdate:	26/04/2017	Fiscalpower:	
Expertise Mileage:	19113	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	1223
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V Steel				
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1807,42
-------------------	----------------

Wheel cover F R, Scratch(es), E - Replace	30,00
---	--------------



Bodywork, Not original part, Remove lettering

0,00



Roof, Scratch(es), Acceptable

0,00

No pictures to display

Tyre F R, Tear, E - Replace

132,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

406,50



Door R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), Le - Replace and paint

530,02



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Centre console, Hole, E - Replace

52,80



Maintenance, Maintenance, Execute

0,00



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Instrument panel cover, Hole, E - Replace 55,80



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 30,00

