


RENAULT Megane: 1FXB999

Vinnumber:	VF1KZ090349855452	Versionname:	MEGANE GT Bose Ed. EDC 110PK Aut.
First Registrationdate:	25/11/2013	Fiscalpower:	
Expertise Mileage:	126548	Power Kw:	81
Bodytype:		Body color	Brown
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3402
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	Tow bar removable
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather and alcantara	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/50/17/89 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	950,24
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Dent(s), Smart repair	110,64



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper corner R R, Dent(s) and scratch(es), It - Spot repair

115,56



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), It - Spot repair

115,56



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80

