



AUDI A4 AVANT: 1KSY223

Vinnumber:	WAUZZZ8K0FA148298	Versionname:	2.0 TDI 140KW S TRONIC QUATTRO
First Registrationdate:	25/06/2015	Fiscalpower:	
Expertise Mileage:	46576	Power Kw:	140
Bodytype:	Break	Body color:	Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Wheel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2613
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	CD
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/50/17/94 Y LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1907,24
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Bumper R, Scratch(es), LI - Repair and paint (complete)

235,80



Windscreen, Stone chip(s), Acceptable

0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,50
---	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display