



PEUGEOT 5008: 1NSX529

Vinnumber:	VF30ABHXMG5099181	Versionname:	1.6 BLUEHDI S&S 85KW ACTIVE
First Registrationdate:	19/04/2016	Fiscalpower:	
Expertise Mileage:	131030	Power Kw:	85
Bodytype:	SUV	Body color	Light Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3422
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/55/16/93 V LightMetal			
	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm

Assistance equipment

Total cost ex VAT	2779,72
Bumper F, Broken, Le - Replace and paint	735,00





Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Wing R L, Scratch(es), 67 - Polish

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing L, Scratch(es), Smart repair

110,64



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------




Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Reflector, Broken, E - Replace	20,00
--------------------------------	-------



Rearview mirror housing R, Scratch(es), 67 - Polish	55,19
---	-------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Interior, Dirty, Cleaning	50,00
---------------------------	-------



