



#### SKODA OCTAVIA COMBI: 1JSS324

|                                    |                          |              |                                         |
|------------------------------------|--------------------------|--------------|-----------------------------------------|
| Vinnumber:                         | <b>TMBJG7NE0F0170218</b> | Versionname: | <b>1.6 CRTDI 77KW GREENTEC AMBITION</b> |
| First Registrationdate:            | <b>16/02/2015</b>        | Fiscalpower: |                                         |
| Expertise Mileage:                 | <b>107005</b>            | Power Kw:    | <b>77</b>                               |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Black</b>                            |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metallic</b>                         |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                        |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                               |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2403</b>                             |
| Number of doors:                   | <b>5</b>                 |              |                                         |
| Number of seats:                   | <b>5</b>                 |              |                                         |
| Number head rests:                 | <b>5</b>                 |              |                                         |
| Rims summer:                       | <b>Aluminium</b>         |              |                                         |
| Category:                          | <b>Passenger Car</b>     |              |                                         |
| Oil level:                         | <b>OK</b>                |              |                                         |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                         |

#### Options

|                                |                              |                       |                          |
|--------------------------------|------------------------------|-----------------------|--------------------------|
| Radio CD                       |                              | Central consol F      |                          |
| GPS storage                    | <b>SD</b>                    | Luggage cover         |                          |
| GPS storage                    |                              | Front parking sensors |                          |
| Windows electric F             |                              | Rear parking sensors  |                          |
| Windows electric R             |                              | Type of Tow bar       | <b>Tow bar removable</b> |
| Cruise Control                 |                              |                       |                          |
| Steering wheel multifunctional |                              |                       |                          |
| Seats F heated                 |                              |                       |                          |
| Radio multimedia               |                              |                       |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                          |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |                          |
| Type of climate control        | <b>Autom climate control</b> |                       |                          |

#### Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

#### Degree of wear

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/55/16/91 T LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Michelin: 4 mm</b> | Fr.R. | <b>Goodyear: 6 mm</b> |
|               | Re.L.                            | <b>Michelin: 4 mm</b> | Re.R. | <b>Goodyear: 6 mm</b> |

#### Assistance equipment

|                                          |            |            |            |
|------------------------------------------|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|                   |         |
|-------------------|---------|
| Total cost ex VAT | 1693,25 |
|-------------------|---------|

|                                   |      |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                                                     |        |
|---------------------------------------------------------------------|--------|
| Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) | 308,20 |
|---------------------------------------------------------------------|--------|



Tailgate, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Rear spoiler, Dent(s), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



|                                                             |        |
|-------------------------------------------------------------|--------|
| Door R L, Scratch(es), Acceptable                           | 0,00   |
| No pictures to display                                      |        |
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 290,08 |



|                                               |       |
|-----------------------------------------------|-------|
| Door F R, Dent(s) and scratch(es), Acceptable | 0,00  |
| No pictures to display                        |       |
| Floor covering F L, Hole, Smart repair        | 64,32 |

