



CITROEN C3: GS7279

Vinnumber:	VF7SC9HPKDW605521	Versionname:	C3 BER e-Hdi Business GPS (Fleet)92PK
First Registrationdate:	23/08/2013	Fiscalpower:	
Expertise Mileage:	169185	Power Kw:	68
Bodytype:	Hatchback	Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1716
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	185/65/15/88 T Steel			
	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1659,18
Wheel cover R L, Scratch(es), E - Replace			24,00





Wheel cover F R, Scratch(es), E - Replace

24,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair

201,60



Rear window, Scratch(es), E - Replace

320,00



Ceiling, Stain, Cleaning

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44

Bumper R, Scratch(es), LI - Repair and paint (complete)		189,77
		
Door R R, Scratch(es), LI - Repair and paint (complete)		254,68
		
Door F R, Scratch(es), LI - Repair and paint (complete)		254,68
		
Wheel cover R R, Scratch(es), Acceptable		0,00
		
Door R L, Scratch(es), Acceptable		0,00
No pictures to display		
Tailgate, Dent(s), LI - Repair and paint (complete)		241,34
		
Wing F R, Scratch(es), Acceptable		0,00
No pictures to display		
Wheel cover F L, Scratch(es), Acceptable		0,00
No pictures to display		