


**MERCEDES A 160 : 1JXD467**

|                                   |                                |              |                |
|-----------------------------------|--------------------------------|--------------|----------------|
| Vinnumber:                        | <b>WDD1760111V059983</b>       | Versionname: | <b>CDI</b>     |
| First Registrationdate:           | <b>11/03/2015</b>              | Fiscalpower: |                |
| Expertise Mileage:                | <b>107164</b>                  | Power Kw:    | <b>66</b>      |
| Bodytype:                         |                                | Body color   | <b>Black</b>   |
| Gearbox:                          | <b>MAN 6 VIT</b>               | Paint type   | <b>Metalic</b> |
| Transmission:                     | <b>Front</b>                   | Rims summer  | <b>Steel</b>   |
| Fueltype:                         | <b>Diesel</b>                  | Oil level    | <b>OK</b>      |
| Maintenance                       | <b>NOT OK</b>                  | Parking lot  | <b>3603</b>    |
| Maintenance                       | <b>DEPASSER DEPUIS 6 JOURS</b> |              |                |
| Battery functioning               | <b>Yes</b>                     |              |                |
| Number of doors                   | <b>5</b>                       |              |                |
| Number of seats                   | <b>5</b>                       |              |                |
| Number head rests                 | <b>5</b>                       |              |                |
| Rims summer                       | <b>Steel</b>                   |              |                |
| Category                          | <b>Passenger Car</b>           |              |                |
| Oil level                         | <b>OK</b>                      |              |                |
| Registration Certificate Car (BE) | <b>Yes</b>                     |              |                |

**Options**

|                                |                               |
|--------------------------------|-------------------------------|
| Radio CD                       | Central consol F              |
| GPS storage                    | Luggage cover                 |
| GPS storage                    | <b>HD</b>                     |
| Windows electric F             |                               |
| Windows electric R             |                               |
| Cruise Control                 |                               |
| Steering wheel multifunctional |                               |
| Radio multimedia               |                               |
| Type of headlighting           | <b>Headlighting Halogen</b>   |
| Type of GPS                    | <b>GPS big screen color</b>   |
| Type of Lining                 | <b>Lining fabrics</b>         |
| Type of climate control        | <b>Manual climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                      |                  |       |                  |
|---------------|----------------------|------------------|-------|------------------|
| Summer tyres: | 195/65/15/91 H Steel |                  |       |                  |
|               | Fr.L.                | Vredestein: 6 mm | Fr.R. | Vredestein: 6 mm |
|               | Re.L.                | Vredestein: 7 mm | Re.R. | Vredestein: 7 mm |

**Assistance equipment**

|                                        |            |            |                |
|----------------------------------------|------------|------------|----------------|
| Repair kit                             | <b>Yes</b> | Compressor | <b>Yes</b>     |
| Total cost ex VAT                      |            |            | <b>2049,00</b> |
| Backrest cover F R, Stain, Acceptable  |            |            | <b>0,00</b>    |
| <i>No pictures to display</i>          |            |            |                |
| Windscreen, Stone chip(s), E - Replace |            |            | <b>487,20</b>  |



Front end, Scratch(es), Acceptable 0,00

No pictures to display

Ceiling, Stain, Cleaning 50,00



Door panel R R, Dirty, Acceptable 0,00

No pictures to display

Floor covering R, Stain, Cleaning 25,00



Maintenance, Maintenance, Execute 0,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Cleaning 25,00



Door R R, Dent(s), It - Spot repair 115,56



Boot carpet, Stain, Chemical cleaning 50,00



Backrest cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace 30,00



Wheel aperture R L, Scratch(es), Acceptable 0,00

No pictures to display

Door seal F L, Deformed / Strained, E - Replace 54,00



Door panel R L, Hole, Smart repair 110,64



Wheel cover F L, Scratch(es), E - Replace 30,00



Wheel cover F R, Scratch(es), E - Replace 30,00



Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), 67 - Polish 0,00

No pictures to display

Maintenance book, Missing, E - Replace 0,00



Headlight L, Broken, E - Replace 396,00



Roof pillar R, Scratch(es), 67 - Polish 0,00

No pictures to display

|                                                                                                                                                                                                                                                                                                                                                                                                                                     |        |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| Sill trim R, Scratch(es), Acceptable                                                                                                                                                                                                                                                                                                                                                                                                | 0,00   |
| No pictures to display                                                                                                                                                                                                                                                                                                                                                                                                              |        |
| Door F L, Scratch(es), Acceptable                                                                                                                                                                                                                                                                                                                                                                                                   | 0,00   |
| No pictures to display                                                                                                                                                                                                                                                                                                                                                                                                              |        |
| Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)                                                                                                                                                                                                                                                                                                                                                                 | 307,80 |
|   <br>         |        |
| Roof, Scratch(es), 67 - Polish                                                                                                                                                                                                                                                                                                                                                                                                      | 0,00   |
| No pictures to display                                                                                                                                                                                                                                                                                                                                                                                                              |        |
| Wheel cover R R, Scratch(es), E - Replace                                                                                                                                                                                                                                                                                                                                                                                           | 30,00  |
|                                                                                                                                                                                  |        |
| Instruction book, Missing, E - Replace                                                                                                                                                                                                                                                                                                                                                                                              | 0,00   |
| No pictures to display                                                                                                                                                                                                                                                                                                                                                                                                              |        |
| Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)                                                                                                                                                                                                                                                                                                                                                                 | 307,80 |
|   <br>  |        |