


VOLVO V40 CROSS COUNTRY: 1KLE306

Vinnumber:	YV1MZ74L1G2091171	Versionname:	1.6 D2 KINETIC
First Registrationdate:	26/05/2015	Fiscalpower:	
Expertise Mileage:	197834	Power Kw:	84
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2631
Maintenance:	10725KM - 6 MAANDEN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/92 V LightMetal			
	Fr.L.	Vredestein: 8 mm	Fr.R.	Vredestein: 8 mm
	Re.L.	Vredestein: 8 mm	Re.R.	Vredestein: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			579,02
Rocker panel inner R L, Scratch(es), Acceptable			0,00
No pictures to display			
Bonnet, Stone chip(s), Acceptable			0,00
No pictures to display			
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00



Moulding windscreen U, Chemical polution, E - Replace

55,06



Rocker panel inner F L, Scratch(es), Acceptable

0,00

No pictures to display

Interior, Dirty, Cleaning

125,00



Door R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner F R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper trim R, Scratch(es), E - Replace

208,96



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display