



BMW 5 BERLINE: 1JTK321

Vinnumber:	WBA5E31040D672818	Versionname:	2.0 518D (100KW)
First Registrationdate:	20/02/2015	Fiscalpower:	
Expertise Mileage:	144462	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	SERVICE IN 7000KM 1 2020	Parking lot	1204
Maintenance	OK		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Seats electric F L
GPS storage	Seats electric F R
GPS storage	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.
	Re.L.	Michelin: 6 mm	Re.R.

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			507,16
Door R L, Dent(s), PDR - Paintless dent repair			63,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door panel F R, Worn, Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

