



**VOLKSWAGEN GOLF VARIANT: 1KSE040**

|                                   |                          |              |                                      |
|-----------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber:                        | <b>WVWZZZAUZFP625433</b> | Versionname: | <b>1.6 CR TDI 77KW BMT TRENDLINE</b> |
| First Registrationdate:           | <b>22/06/2015</b>        | Fiscalpower: |                                      |
| Expertise Mileage:                | <b>110218</b>            | Power Kw:    | <b>77</b>                            |
| Bodytype:                         |                          | Body color   | <b>Black</b>                         |
| Gearbox:                          | <b>MAN 5 VIT</b>         | Paint type   | <b>Metalic</b>                       |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Steel</b>                         |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                            |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>2307</b>                          |
| Number of doors                   | <b>5</b>                 |              |                                      |
| Number of seats                   | <b>5</b>                 |              |                                      |
| Number head rests                 | <b>5</b>                 |              |                                      |
| Rims summer                       | <b>Steel</b>             |              |                                      |
| Category                          | <b>Passenger Car</b>     |              |                                      |
| Oil level                         | <b>OK</b>                |              |                                      |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                      |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| GPS storage                    | <b>SD</b>                    | Central consol F      |                   |
| GPS storage                    |                              | Luggage cover         |                   |
| Windows electric F             |                              | Front parking sensors |                   |
| Windows electric R             |                              | Rear parking sensors  |                   |
| Cruise Control                 |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Steering wheel multifunctional |                              |                       |                   |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                      |                   |       |                   |
|---------------|----------------------|-------------------|-------|-------------------|
| Summer tyres: | 195/65/15/91 H Steel |                   |       |                   |
|               | Fr.L.                | Continental: 4 mm | Fr.R. | Continental: 4 mm |
|               | Re.L.                | Continental: 5 mm | Re.R. | Continental: 5 mm |

**Assistance equipment**

|                                          |            |      |            |
|------------------------------------------|------------|------|------------|
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 236,80 |
|-------------------|--------|

|                               |      |
|-------------------------------|------|
| Tailgate, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                                  |       |
|--------------------------------------------------|-------|
| Rear window, Not original part. Remove lettering | 25,00 |
|--------------------------------------------------|-------|



|                                                    |      |
|----------------------------------------------------|------|
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
|----------------------------------------------------|------|

No pictures to display

|                                               |      |
|-----------------------------------------------|------|
| Trunk lid covering R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------------------|------|

No pictures to display

|                                                         |        |
|---------------------------------------------------------|--------|
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---------------------------------------------------------|--------|



|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                          |      |
|--------------------------|------|
| Ceiling, Stain, Cleaning | 0,00 |
|--------------------------|------|



|                               |      |
|-------------------------------|------|
| Seat cover R, Stain, Cleaning | 0,00 |
|-------------------------------|------|



|                                  |      |
|----------------------------------|------|
| Door R R, Bad repair, Acceptable | 0,00 |
|----------------------------------|------|



|                               |      |
|-------------------------------|------|
| Wing F L, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display