



# CITROEN GRAND C4 PICASSO: 1PLY196

|                                    |                   |              |                                    |
|------------------------------------|-------------------|--------------|------------------------------------|
| Vinnumber:                         | VF73ABHXTGJ701717 | Versionname: | 1.6 BLUEHDI 115 S/S INTENSIVE AUTO |
| First Registrationdate:            | 8/08/2016         | Fiscalpower: |                                    |
| Expertise Mileage:                 | 168269            | Power Kw:    | 85                                 |
| Bodytype:                          |                   | Body color:  | Red                                |
| Gearbox:                           | Automatic         | Paint type:  | Metallic                           |
| Transmission:                      | Front             | Rims summer: | Aluminium                          |
| Fueltype:                          | Diesel            | Oil level:   | OK                                 |
| Maintenance:                       | OK                | Parking lot: | 3115                               |
| Battery functioning:               | Yes               |              |                                    |
| Number of doors:                   | 5                 |              |                                    |
| Number of seats:                   | 7                 |              |                                    |
| Number head rests:                 | 7                 |              |                                    |
| Rims summer:                       | Aluminium         |              |                                    |
| Category:                          | Passenger Car     |              |                                    |
| Oil level:                         | OK                |              |                                    |
| Registration Certificate Car (BE): | Yes               |              |                                    |

## Options

|                                |                       |                       |            |
|--------------------------------|-----------------------|-----------------------|------------|
| GPS storage                    | HD                    | Central consol F      |            |
| GPS storage                    |                       | Luggage cover         |            |
| Windows electric F             |                       | Front parking sensors |            |
| Windows electric R             |                       | Rear parking sensors  |            |
| Cruise Control                 |                       | Type of Tow bar       | No Tow bar |
| Steering wheel multifunctional |                       |                       |            |
| Type of headlighting           | Headlighting Halogen  |                       |            |
| Type of GPS                    | GPS big screen color  |                       |            |
| Type of Lining                 | Lining fabrics        |                       |            |
| Type of climate control        | Autom climate control |                       |            |

## Limited Technical Inspection

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Power steering      | Yes |
| Idle position       | OK | Sound engine        | OK  |
| Engine startingtime | OK | Clutch test         | OK  |
| Exhaust gass        | OK | Wiper fluid level   | OK  |
| Handbrake           | OK | Transmission        | OK  |
|                     |    | Lighting            | OK  |
|                     |    | Wiperblades         | OK  |

## Degree of wear

|               |                           |                |       |                |
|---------------|---------------------------|----------------|-------|----------------|
| Summer tyres: | 205/60/16/91 H LightMetal |                |       |                |
|               | Fr.L.                     | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
|               | Re.L.                     | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

## Assistance equipment

|                                          |    |            |     |
|------------------------------------------|----|------------|-----|
| Repair kit                               | No | Compressor | Yes |
| Number of charging cables (normal)       | 0  |            |     |
| Number of charging cables (rapid charge) | 0  |            |     |

|                                                                     |         |
|---------------------------------------------------------------------|---------|
| Total cost ex VAT                                                   | 1065,15 |
| Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) | 318,35  |



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Door frame F L, Dent(s), Acceptable

0,00

*No pictures to display*

Door F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Ceiling, Stain, Cleaning

25,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Door R L, Dent(s), PDR - Paintless dent repair

106,80



Door R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

