



BMW 5 TOURING: 1KVN366

Vinnumber:	WBA5L31060G081782	Versionname:	2.0 520D (120KW) TOURING
First Registrationdate:	14/07/2015	Fiscalpower:	
Expertise Mileage:	177810	Power Kw:	120
Bodytype:	Break	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1324
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	No Tow bar
Type of GPS	Headlighting Halogen
Type of Lining	GPS big screen color
Type of climate control	Lining leather
Adaptive cruise control	Autom climate control

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	245/45/18/96 V LightMetal			
	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Total cost ex VAT	1270,34
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,16



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00




Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Sill outer L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

		
Tailgate, Scratch(es), Acceptable		0,00
No pictures to display		
Door F R, Scratch(es), LI - Repair and paint (complete)		382,02

		
Rearview mirror housing R, Scratch(es), 67 - Polish		0,00
No pictures to display		