



# AUDI A3 SPORTBACK: 1KVV958

|                                    |                   |              |                                    |
|------------------------------------|-------------------|--------------|------------------------------------|
| Vinnumber:                         | WAUZZZ8V5GA016441 | Versionname: | 1.6 TDI ULTRA ATTRACTION SPORTBACK |
| First Registrationdate:            | 16/07/2015        | Fiscalpower: |                                    |
| Expertise Mileage:                 | 130866            | Power Kw:    | 81                                 |
| Bodytype:                          | Hatchback         | Body color:  | Black                              |
| Gearbox:                           | MAN 6 VIT         | Paint type:  | Metallic                           |
| Transmission:                      | Front             | Rims summer: | Aluminium                          |
| Fueltype:                          | Diesel            | Oil level:   | OK                                 |
| Battery functioning:               | Yes               | Parking lot: | 3623                               |
| Number of doors:                   | 5                 |              |                                    |
| Number of seats:                   | 5                 |              |                                    |
| Number head rests:                 | 5                 |              |                                    |
| Rims summer:                       | Aluminium         |              |                                    |
| Category:                          | Passenger Car     |              |                                    |
| Oil level:                         | OK                |              |                                    |
| Registration Certificate Car (BE): | Yes               |              |                                    |

## Options

|                                |                       |
|--------------------------------|-----------------------|
| Radio CD                       | Central consol F      |
| GPS storage                    | Luggage cover         |
| GPS storage                    | SD                    |
| Windows electric F             | Rear parking sensors  |
| Windows electric R             | Type of Tow bar       |
| Steering wheel multifunctional | No Tow bar            |
| Radio multimedia               |                       |
| Type of headlighting           | Headlighting Halogen  |
| Type of GPS                    | GPS big screen color  |
| Type of Lining                 | Lining fabrics        |
| Type of climate control        | Autom climate control |

## Limited Technical Inspection

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Power steering      | Yes |
| Idle position       | OK | Sound engine        | OK  |
| Engine startingtime | OK | Clutch test         | OK  |
| Exhaust gass        | OK | Wiper fluid level   | OK  |
| Handbrake           | OK | Transmission        | OK  |
|                     |    | Lighting            | OK  |
|                     |    | Wiperblades         | OK  |

## Degree of wear

| 205/55/16/91 V LightMetal |       |                |                |
|---------------------------|-------|----------------|----------------|
| Summer tyres:             | Fr.L. | Michelin: 4 mm | Fr.R.          |
|                           | Re.L. | Michelin: 5 mm | Re.R.          |
|                           |       | Michelin: 4 mm | Michelin: 5 mm |

## Assistance equipment

|                                          |     |            |     |
|------------------------------------------|-----|------------|-----|
| Repair kit                               | Yes | Compressor | Yes |
| Number of charging cables (normal)       | 0   |            |     |
| Number of charging cables (rapid charge) | 0   |            |     |

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 820,23 |
|-------------------|--------|

|                                   |      |
|-----------------------------------|------|
| Wing F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                |      |
|--------------------------------|------|
| Door F L, Repaired, Acceptable | 0,00 |
|--------------------------------|------|

No pictures to display


Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)

290,08



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Roof, Dent(s), Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35

