



#### AUDI A3 SPORTBACK: 1KVV948

|                                   |                          |              |                              |
|-----------------------------------|--------------------------|--------------|------------------------------|
| Vinnumber:                        | <b>WAUZZZ8V3FA184397</b> | Versionname: | <b>1.6 TDI 81KW AMBIENTE</b> |
| First Registrationdate:           | <b>16/07/2015</b>        | Fiscalpower: |                              |
| Expertise Mileage:                | <b>191076</b>            | Power Kw:    | <b>81</b>                    |
| Bodytype:                         | <b>Hatchback</b>         | Body color   | <b>Black</b>                 |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metallic</b>              |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b>             |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                    |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>2121</b>                  |
| Number of doors                   | <b>5</b>                 |              |                              |
| Number of seats                   | <b>5</b>                 |              |                              |
| Number head rests                 | <b>5</b>                 |              |                              |
| Rims summer                       | <b>Aluminium</b>         |              |                              |
| Category                          | <b>Passenger Car</b>     |              |                              |
| Oil level                         | <b>OK</b>                |              |                              |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                              |

#### Options

|                                |                              |
|--------------------------------|------------------------------|
| Windows electric F             | Central consol F             |
| Windows electric R             | Luggage cover                |
| Cruise Control                 | Front parking sensors        |
| Steering wheel multifunctional | Rear parking sensors         |
| Seats F heated                 | Type of Tow bar              |
| Radio multimedia               | <b>Tow bar removable</b>     |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

#### Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |


#### Degree of wear

|               |                           |                   |       |                   |
|---------------|---------------------------|-------------------|-------|-------------------|
| Summer tyres: | 205/55/16/91 W LightMetal |                   |       |                   |
|               | Fr.L.                     | Continental: 4 mm | Fr.R. | Continental: 4 mm |
|               | Re.L.                     | Continental: 5 mm | Re.R. | Continental: 5 mm |

#### Assistance equipment

|                                          |            |            |            |
|------------------------------------------|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|                                                           |        |
|-----------------------------------------------------------|--------|
| Total cost ex VAT                                         | 633,50 |
| Roof, Chemical polution, LI - Repair and paint (complete) | 529,50 |



|                                                |        |
|------------------------------------------------|--------|
| Bumper F, Scratch(es), Acceptable              | 0,00   |
| No pictures to display                         |        |
| Bumper R, Scratch(es), Acceptable              | 0,00   |
| No pictures to display                         |        |
| Bonnet, Dent(s), Acceptable                    | 0,00   |
| No pictures to display                         |        |
| Rearview mirror housing L, Broken, E - Replace | 104,00 |

