


AUDI A3: 1HLG273

Vinnumber:	WAUZZZ8V4EA175433	Versionname:	A3 SB Ambition 136PK
First Registrationdate:	19/08/2014	Fiscalpower:	
Expertise Mileage:	123944	Power Kw:	100
Bodytype:	Hatchback	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4305
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 Y LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3037,66
Sill outer R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Boot cover, Broken, E - Replace 50,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00



Rearview mirror R complete, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	290,08
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	414,35
---	--------



Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display